

LATHE MACHINE OPTIONAL ACCESSORIES

OPTIONAL ACCESSORY	SPECIFICATIONS	CU325	CU360M	C400TM	CU400	CU500	CU400M	CU500M	CU580M	C11MT	CU500MT	CU630	CU730	C10T	C10TM	C10TH	CU660	CU760	CU800	CU1000	CU1250	
3-JAW SELF-CENTERING CHUCK	Diameter (mm)	160	200	200	250	250	250	250	250	250	315	315	315	315	400	400	315	315	400	500	500	
INDEPENDENT 4-JAW CHUCK	Diameter (mm)	250	320	320	400	500	400	500	500	500	500	600	600	600	600	600	600	600	760	1000	1000	
FACE PLATE	Diameter (mm)	296	320	320	400	480	400	480	480	480	500	600	600	600	600	600	600	600	760	1000	1000	
FOLLOWE REST	Range (mm)	10-70	10-80	10-80	15-160	15-200	15-160	15-200	15-200	15-200	15-200	15-200	15-200	20-200	20-200	50-250	20-200	20-200	80-300	80-300	80-300	
STEADY REST, SMALL SIZE	Range (mm)	10-70	10-100	10-100	15-150	15-160	15-160	15-160	15-200	15-200	15-160	15-200	15-200	20-200	20-200	50-250	20-200	20-200	50-300	50-300	50-300	
STEADY REST, BIG SIZE	Range (mm)	No	No	No	No	140-280	No	140-280	180-340	180-340	140-280	180-340	180-430	180-430	180-430	220-450 200-520	180-430	200-520	270-520	270-520 480-720	270-520 480-720 700-950	
TAPER TURNING ATTACHM.	$\pm 10^0$	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	
ONE-POSITION LONG. STOP		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	No	No	No
THREAD DIAL		Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	Yes	
DRIVE PLATE FOR SPINDLE NOSE DIN 55027	Diameter (mm) Spindle nose No	230 / N5	250/N6	250 / N6	300 / N8	300 / N8	300 / N8	300 / N8	300 / N8	300 / N8	320 / N11	320 / N11	320 / N11	320 / N11	320 / N11	320 / N11	320 / N11	320 / N11	No	No	No	
SET OF LATHE DOGS	Ø20; Ø30; Ø40; Ø50; Ø60; Ø80; Ø100	20; 50;	20;30;40; 50;60	20; 30; 40;50;60	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	Full Set	No	No	No	
LIVE CENTER	Morse	M3	M4	M4	M5	M5	M5	M5	M5	M5	M5	M5	M5	M5	M6	M6	M6	M6	M6	M6	M6	
DRILL CHUCK WITH ARBOR	Drill diam. (mm)	13	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	20	No	No	No	

Remarks : Yes = Available for this model;

No = Not available for this model

Steady rest Ø720 for lathe CU1000 – open type only